



An Exelon Company

BGE Safety Escort Process

A BGE Safety Escort is required to gain access to any secure BGE facility, such as a substation or Service Center. To gain access into one of these areas, please follow the steps below:

1. Contact the Exelon Security Operations Center (ESOC) at 800-550-6154 to request an escort or obtain access codes.
Note: BGE Site ID's must be provided when requesting access to a site.
2. LightSpeed personnel will then contact you to set up your requested escort.
3. Please allow three business days for standard service. Emergency escorts will be provided within 24 hours of the request for a true emergency.

For access to sites currently under construction or in the planning stages, your LightSpeed Construction Manager will schedule a safety escort, as required.

Substations require additional precautions for safety; therefore when you are escorted into a substation, you will be required to wear the following Personal Protective Equipment (PPE):

- ❖ Hard Hat
- ❖ Safety Glasses
- ❖ Hard-Soled/Steel Toe Boots
- ❖ Fire Retardant (FR) Clothing (we will provide jumpsuits if you do not have your own)
- ❖ 100% cotton clothing underneath the FR clothing

Escorts are provided at the customer's expense as defined in the lease agreement.